MID-ATLANTIC HISTORIC BUILDINGS SURVEY INDEX TO PHOTOGRAPHS

4127 Concord Pike Talleyville vicinity Brandywine Hundred New Castle County, Delaware CRS # N-4052 CHAD # 0188-N-2003

Location of original negatives: Center for Historic Architecture and Design, University of Delaware, Newark, DE

Photographer: Rebecca J. Sheppard

December 2003

Frame number

- 5 Perspective of west and south elevations of house and garage, looking Northwest
- 8 Perspective of north and west elevations of house, looking southeast
- 14 Interior, first floor: view of stair on north wall in west room, looking north
- 15 Interior, first floor: view of fireplace on south wall in west room, looking Southeast
- 23 Interior, first floor: view of original window and German siding on north wall of enclosed porch, looking northwest
- 32 Interior, second floor: view of attic stairs looking northeast
- 33 Interior, attic: view looking southwest
- 37 Interior, first floor: detail of hinges on Dutch door in the kitchen





















